

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

991  
East  
> 1  
1.300 mi.  
6864 ft.

NY Spills S108982286  
N/A

Relative:  
Higher

SPILLS:

Actual:  
9 ft.

Name: KOPELOWITZ HOME  
Address: 79 CORBIN PLACE  
City,State,Zip: BRIGHT BEACH, NY 11235  
Spill Number/Closed Date: 0711095 / 2008-02-25  
Facility ID: 0711095  
Facility Type: ER  
DER Facility ID: 342113  
Site ID: 392513  
DEC Region: 2  
Spill Cause: Equipment Failure  
Spill Class: B3  
SWIS: 2401  
Spill Date: 2008-01-21  
Investigator: jbvought  
Referred To: Not reported  
Reported to Dept: 2008-01-21  
CID: 408  
Water Affected: Not reported  
Spill Source: Private Dwelling  
Spill Notifier: Other  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: Not reported  
Remediation Phase: 0  
Date Entered In Computer: 2008-01-22  
Spill Record Last Update: 2008-02-25  
Spiller Name: RABBI KOPELOWITZ  
Spiller Company: PRIVATE HOME  
Spiller Address: 79 CORBIN PLACE  
Spiller Company: 001  
Contact Name: RABBI KOPELOWITZ  
DEC Memo: "1/22/08 - Raphael Ketani. I sent a CSL to Rabbi Kopelowitz.  
2/4/08-Vought-Vought spoke to Joseph Samsonowitz (516-655-6606) and  
as per Joseph no oil spill occurred and staining was due to water.  
Tank is located under stairway and is 275-gallon #2 fuel oil AST. No  
oil odors in building. DEC suggested testing but not required as tank  
is under 1100-gallons. Contact is Vinny (Tank Doctor 718-727-0666)  
and as per Vinny staircase above tank is cracked. Tank may have been  
overfilled. Vinny instructed Joseph to observe tank during fill to  
see if seepage continued once fill was delivered. Vought called  
Joseph and left message informing him of conversation with Vinny and  
with contact information of DEC Zhune and that no further deliveries  
should take place and that tank should be tightness tested. DEC  
requires: 1)Tightness testing of tank. 02/26/08-Vought-Received call  
from Mr Samsonowitz (516-655-6606) and returned call and spoke to Mr.  
Corbin and ATF Testing Service came and that tank passed test. Mr.  
Samsonowitz will fax in tightness test results and case will be  
closed upon receipt and review of test results and closure letter  
will be sent to: Mr. Joseph Samsonowitz 728 Beach 9th Street Far  
Rockaway, NY 11691 Vought received faxed copy from Advanced Tank  
Services (Gary Harris 800-440-8265) and Advanced Tank Services Co.

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

certifies that the 300 gallon underground #2 heating oil storage tank and distribution lines located at 79 Corbin Place, Brooklyn, NY did not contain any detectable leaks after a EZY3 Locator Plus test was performed. Spill closed by Vought and NFA sent to above address after spill reassignment from Zhune to Vought."

Remarks: "TANK IS LEAKING; NOT FULLY BURIED BUT IT IS HALF IN THE GROUND;"

All TTF:

Facility ID: 0711095  
Spill Number: 0711095  
Spill Tank Test: 2384519  
Site ID: 392513  
Tank Number: Not reported  
Tank Size: 275  
Material: 0001  
EPA UST: Not reported  
UST: False  
Cause: 00  
Source: 01  
Test Method: 00  
Test Method 2: Unknown  
Leak Rate: .00  
Gross Fail: Not reported  
Modified By: Watchdog  
Last Modified Date: Not reported

All Materials:

Site ID: 392513  
Operable Unit ID: 1149507  
Operable Unit: 01  
Material ID: 2140032  
Material Code: 0001A  
Material Name: #2 fuel oil  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: Not reported  
Units: G  
Recovered: .00  
Oxygenate: False